RPII Inspector Issued Report

Issued by: Elliotts Inspections

Date Issued: 11/05/2026

Date Expires: 11/05/2027

RPII Reg Number: AI0223

Place of Inspection: On site at customer location

Unique Report Number: 195

Result: Passed Inspection

Unit Details

Description: Unicorn Toddler Play Zone
Manufacturer: Better Bounce
Size (m): Width: 4.6 Length: 4.6 Height: 2.1
Serial: 68582
Unit Type: Toddler Play Zone
Unit Owner: Elliotts Bouncy Castle Hire

User Height/Count

Containing Wall Height: 1.6m
Comment: Lowest wall height taken from adjacent platform.
Tallest Platform Height: 0.84m
Comment:
Tallest User Height: 1.2m
Comment: Calculated using lowest containing wall height minus the platform height or the relevant slide calculations where appropriate.
Internal Play Area Length: 3.3m
Comment:
Internal Play Area Width: 3.3m
Comment:
Negative Adjustment: 0m
Comment: Approx square metre taken by obstacles, biff bash, mounds etc.
Users @ 1.0m: 8 Users @ 1.2m: 8 Users @ 1.5m: 0 Users @ 1.8m: 0

Slide

Slide Platform Height: 0.84m
Comment:
Containing Wall Height: 0.6m
Comment: Lowest wall height taken from the slide platform height.
First Metre Slide Wall Height: 0.6
Comment:
Remaining Slide Wall Height: 0.6m
Comment:
Perm Slide Roof Fitted: True
Comment:
Steps/Clamber Netting Pass/Fail: True
Comment: Not monofilament, no entrapment and at least 12mm diameter, securely knotted and no fraying, securely fastened.
Slide Run Out: 0.7m
Slide Run Out Pass/Fail: True
Comment: Slide Run-out is at least 50% of slide platform height.
Slip Sheet Integrity Pass/Fail: True
Comment: Slip sheet has no tears, causes no entrapment and is securely fastened.

RPII Inspector Issued Report

Issued by: Elliotts Inspections

Date Issued: 11/05/2026

Date Expires: 11/05/2027

RPII Reg Number: AI0223

Place of Inspection: On site at customer location

Unique Report Number: 195

Result: Passed Inspection

Structure

Seam Integrity Pass/Fail: True
Comment: Secure and no loose stitching.
Lock Stitching Pass/Fail: True
Comment: Lock stitching used.
Stitch Length: 4mm
Stitch Length Pass/Fail: True
Comment: Stitching between 3mm - 8mm
Air Loss Pass/Fail: True
Comment: No significant air loss or unintended holes.
Walls and Turrets Vertical Pass/Fail: True
Comment: Walls Vertical and gradient no greater than +-5% where intended.
Sharp/Square/Pointed Edges Pass/Fail: True
Comment: No sharp or pointed edges in play area or easily accessible.
Blower Tube Distance: 1.20m
Blower Tube Pass/Fail: True
Comment: Inflate blower tube is at least 1.2m from edge of cone to inflatable.
Unit Stable Pass/Fail: True
Comment: Unit is stable.
Evacuation Time: 30
Evacuation Time Pass/Fail: True
Comment: Evacuation time sufficient for intended users to exit safely under supervision.
Step/Ramp Size: 0m
Step/Ramp Size Pass/Fail: True
Comment: n/a
Critical Fall Off Height: 0.48m
Critical Fall Off Height Pass/Fail: True
Comment: Critical Fall Off Height is a max of 0.48m
Critical Fall Off Height: 0.48m
Critical Fall Off Height Pass/Fail: True
Comment: Critical Fall Off Height is a max of 0.48m
Unit Pressure: 1.10Kpa
Unit Pressure Pass/Fail: True
Comment: Pressure is a minimum of 1.10 KPA
Trough Depth: 70mm
Trough Adjacent Panel Width: 460mm
Trough Pass/Fail: True
Comment: Trough Depth is no more than one third (1/3) of the adjacent panel width.
Entrapment Pass/Fail: True
Comment: No entrapments.
Markings/ID Pass/Fail: True
Comment: Blower, User Height, Max Users, Unique ID, Year of Manufacture & Address and Standard Version.
Grounding Pass/Fail: True
Comment: 25kg @ 1m, 35kg @ 1.2m, 65kg @ 1.5m and 85kg @ 1.8m

RPII Inspector Issued Report

Issued by: Elliotts Inspections

Date Issued: 11/05/2026

Date Expires: 11/05/2027

RPII Reg Number: AI0223

Place of Inspection: On site at customer location

Unique Report Number: 195

Result: Passed Inspection

Anchorage

Total Number of Anchors: 13
Number of Base Anchors: 13
Number of High Anchors: 0
Number of Anchors Pass/Fail: True
Comment: Calculated sufficient number of anchor points per side.
Anchor Accessories Pass/Fail: True
Comment: Produced correct amount of stakes at 380mmx16mm with rounded top and no visible cracks.
Anchors Between 30-45° Pass/Fail: True
Comment: Anchors are at an angle to the ground of 30° to 45°
Anchors Perm Closed Pass/Fail: True
Comment: Metal and permanently closed.
Pull Strength Pass/Fail: True
Comment: Meets the 1600 newton pull requirement test using 163kg pull system

Totally Enclosed

Number of Exits: 0
Number of Exits Pass/Fail: False
Comment: Not Applicable
Number of Exits Pass/Fail: False
Comment: Not Applicable

Materials

Ropes: 18mm
Ropes Pass/Fail: True
Comment: Between 18mm - 45mm. Fixed at both ends, no greater than 20% swing to prevent strangulation.
Clamber Netting Pass/Fail: True
Comment: Not monofilament, no entrapment and at least 12mm diameter, securely knotted and no fraying, securely fastened.
Retention Netting Pass/Fail: True
Comment: Vertical netting > 1m mesh size is no greater than 30mm. Roof neeting mesh size no greater than 8mm.
Zips Pass/Fail: True
Comment: Zips easily open/close and covered. Open both sides where applicable.
Windows Pass/Fail: True
Comment: Retention netting strong enough to support heaviest user for whom it is designed. No entrapment.
Artwork Pass/Fail: True
Comment: Not flaking - Manufacturer to supply conformity report to EN 71-3
Thread Pass/Fail: True
Comment: Manufacturer to provide conformity report to confirm thread is non-rotting yarn and has a tensile strength of 88 newtons.
Fabric Strength Pass/Fail: True
Comment: Manufacturer to provide conformity report to confirm tensile strength of 1850 and tear stength of 350 newtons.
Fire Retardent Pass/Fail: True
Comment: Manufacturer to provide conformity report to confirm FR.

RPII Inspector Issued Report

Issued by: Elliotts Inspections

Date Issued: 11/05/2026

Date Expires: 11/05/2027

RPII Reg Number: AI0223

Place of Inspection: On site at customer location

Unique Report Number: 195

Result: Passed Inspection

Toddler Zone/Play Zone

Marking present to indicate age range: True
Comment: Markings show that user age range is Approx. 1-3 years.
Marking present to indicate max. user height: True
Comment: Markings show that max user height is 1 meter.
Sight lines clear to observe playing areas: True
Comment: Unrestricted view possible for supervisors of all playing areas within the toddler-play zone itself.
Access, Egress and Connections safe: True
Comment: Safe access for movement for carers and users. Steps easily negotiable.
Suitable Matting: True
Comment: Suitable impact absorbing matting is provided at the ends of slides, bouncing areas and ball pits. Matting is at least 20mm thick and covers entire base.
Traffic flow design safe: True
Comment: Pathways clear for users to see path ahead. Design minimises and discourages lingering in pathways of forced motion and ball pits.
Air Jugglers Compliant: True
Comment: Not sharp, pass probe test and do not form finger entrapment, not rigidly set and can collapse under pressure from any user.
Balls Compliant: True
Comment: Balls presented are a minimum of 60mm diameter and have a CE marking.
No gaps in Ball Pool: True
Comment: No gaps present in ball pool that enable objects to become lodged, causing a hazard.
Fitted base sheet: True
Comment: Fitted base/ground sheet sewn in that prevents entrapment or accessing any underside area of walled/contained areas (such as ball pools).
Ball Pool Depth (mm): 400
Ball Pool Depth Pass: True
Comment: Ball Pool Depth is a maximum of 450mm or has a clearly marked max fill line.
Ball Pool Entry Height (mm): 400
Ball Pool Entry Height Pass: True
Comment: The highest point of entry or accessible platform into the ball pool is no greater than a maximum of 630mm.
Platform Incline Gradient (deg): 60
Platform Incline Gradient Pass: True
Comment: The slide platform gradient (access to the platform, not the slide gradient itself) is no greater than 64 degrees.
Slide Platform Height (m): 0.84
Slide Platform Height Pass: True
Comment: The slide platform height is no greater than 1.5m

RPII Inspector Issued Report

Issued by: Elliotts Inspections

Date Issued: 11/05/2026

Date Expires: 11/05/2027

RPII Reg Number: AI0223

Place of Inspection: On site at customer location

Unique Report Number: 195

Result: Passed Inspection

Fan/Blower

Blower Size: Reaches 1.0 kpa pressure on a 1.5hp blower.
Return Flap Pass/Fail: True
Finger Probe Test Pass/Fail: True
Comment: 8mm finger probe does not pass and come into contact with any hot or moving part.
PAT Test Pass/Fail: True
Comment: Customer own certificate.
Visual Inspection Pass/Fail: True
Comment: Passes visual inspection and suitable.
Blower Serial: ebch1.5hp

Risk Assessment

The suitability of all materials used in manufacturing should be taken from conformity reports. Where not available these should be requested from the manufacturer/importer.
Safety aspects should be taken from the user manual provided by the manufacturer. If not provided then this should be requested or created by the controller.
Not to be used in wind speeds in excess of 38Kph.
A competent adult should supervise the inflatable and users at all times.
All anchor points to be used at all times.

Advisory: Operations Manual not presented at time of inspection. Controller advised to obtain or develop the operations manual to ensure that they can demonstrate their duty, safe use and set-up.

Inflatable device inspected for outdoor and indoor use.

Testimony: I certify that the equipment identified above was inspected and complied with the safety criteria required using all relevant sections of the European Standard EN 14960:2019 on the above date.

Inflatable Photo

RPII Inspector Issued Report

Issued by: Elliotts Inspections

Date Issued: 11/05/2026

Date Expires: 11/05/2027

RPII Reg Number: AI0223

Place of Inspection: On site at customer location

Unique Report Number: 195

Result: Passed Inspection

Additional Photo 1

Additional Photo 2

Additional Photo 3

Additional Photo 4